



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Slight Hesitation and/or Sag, DTCs P0101, P0106, P0121, P1101 Set

**Models:** 2016 Chevrolet Express  
2016 GMC Savana  
Equipped with 4.8L or 6.0L Engine (RPOs L20, L96)

### Condition/Concern

Some customers may experience a slight hesitation and/or sag. Upon further inspection, DTCs P0101, P0106, P0121, P1101 may be set.

### Recommendation/Instructions

If following the diagnostic instructions in Service Information (SI) for the codes above does not lead to a root cause, update the ECM. Refer to K20 Engine Control Module: Programming and Setup (Without Diesel) in SI.

### Warranty Information

For vehicles repaired under the Emission coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810075	Engine Control Module Reprogramming with SPS	Use Published Labor Operation Time

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION