Service Bulletin

**Bulletin No.: PIT5453** 

Date: Sep-2015

## PRELIMINARY INFORMATION

Subject: Excessive Brake Wear Or Brake Drag After The Master Cylinder And Booster Are Serviced

Models: 2007-2009 Chevrolet Equinox

2007-2009 Pontiac Torrent

2007-2009 Saturn Vue

## Condition/Concern

The customer may complain of brake noise and/or vehicle drag a short time after the brake booster and master cylinder are serviced. The technician my find excessive brake wear or brake drag.

## Recommendation/Instructions

Please contact GM Technical Assistance for further direction.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safety. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

