



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Gridlines Not Displayed On Rear View Camera Screen

**Models:** 2015 GMC Terrain SLE  
With UFU radio without UP9 or UHQ

### Condition/Concern

A customer may comment that their vehicle does not have gridlines when using the rear view camera system.

The customer may inquire about adding the gridline feature.

### Recommendation/Instructions

For vehicles built prior to 2-10-2015, this was the design intent, but Gridlines can be added to the customer's vehicle.

The radio will need to be programmed to turn this feature on. USB program the radio first followed by GMLAN/SPS programming using the latest version of Radio Programming and Setup in SI.

**Note:** If the radio part number is not listed in the drop down menu during programming, please contact TCSC for programming assistance.

Techline Customer Support Center (TCSC) can be reached at 1-800-828-6860 (English) or 1-800-503-3222 (French).

### Warranty Information

Labor and the reconfiguration fee associated with these procedures should NOT be charged under warranty. Rather, this should be customer pay.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION