

**Bulletin No.: PIC5468E** 

Date: Sep-2015

# Service Bulletin

## PRELIMINARY INFORMATION

Subject: Diagnostic Tip - Spongy Brake Pedal After Hydraulic Brake Component Disconnect Or Replacement - Air

**Trapped In System** 

Models: 2006 - 2013 Chevrolet Impala

2014 - 2016 Chevrolet Impala Limited 2006 - 2007 Chevrolet Monte Carlo

#### This PI was superseded to update model list. Please discard PIC5468D.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

#### Condition/Concern

Some technicians may find that it is difficult to remove all the air from the brake system after ahydraulic component has been disconnected or replaced.

#### Recommendation/Instructions

The brake lines between the master cylinder and the ABS module are routed higher than the mastercylinder reservoir. If air gets into these lines due to a component being disconnected or replaced, it willrise to the high point in the lines. Extra steps must be taken to purge all of the air from the lines.

**Important:** Carefully loosen the fittings on the lines between the master cylinder and the BPMV justenough to be able to rotate the lines temporarily below the fluid level of the reservoir, then tighten thefittings. There is a flexible portion in each of these lines, which makes repositioning possible. Loosenthe fittings just enough to allow the lines to move, not enough to allow air to enter then move the linesback to their original positions and retorque the fittings.

Perform the following Automated Bleed following the steps below exactly as written:

- 1. Install a scan tool.
- 2. Start engine and let idle while performing the Automated Bleed.
- 3. With the scan tool, perform the following steps:
  - 3.1 Select Diagnostics
  - 3.2 Select the appropriate vehicle information
  - 3.3 Select Chassis
  - 3.4 Select Electronic Brake Control Module (EBCM)
  - 3.5 Select Special Functions 3.6 Select Automated Bleed

**Note:** Apply the brake pedal when instructed, using moderate effort.

- 4. Perform the automated bleed procedure, performing only the pump motor activation step of the Tech2 automated bleed procedure. This step must be performed 5 times in a row (exiting after the pump activation and then selecting automated bleed again and then running the first step again). The brake pedal must be depressed the entire time. Do not open any bleeders while performing Automated Bleed.
- 5. After the Five Automated Bleeds have been performed, perform a Gravity Bleed of the system one corner at a time starting with the right rear wheel.
- 6. Repeat step 4 again. After completion of the automated bleed procedure, press and hold the brake pedal to inspect for pedal firmness.
- 7. If the brake pedal feels spongy, repeat the bleed procedure completely
- 8. Adjust the brake fluid level. Refer to Master Cylinder Reservoir Filling.
- 9. Road test the vehicle while confirming the brake pedal remains high and firm.

Note: If concern is still present after performing the above procedure perform published SI document for Hydraulic Brake System Bleeding (Pressure).

### **Warranty Information**

For vehicles repaired under warranty, please use the appropriate warranty labor operation based on the original cause in addition to well documented straight time when using this supplemental bleed procedure

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safety. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

