



Service Bulletin

PRELIMINARY INFORMATION

Subject: XM Weather Tab Will Highlight But Can Not Enter/Access

Models: 2014-2015 Buick LaCrosse, Regal
 2013-2015 Cadillac ATS, SRX, XTS
 2014-2015 Cadillac ELR, CTS Sedan VIN A
 2014-2015 Chevrolet Corvette, Impala VIN 1, Silverado 1500
 2014 GMC Sierra 1500
 2015 Cadillac Escalade models
 2015 Chevrolet Colorado, Silverado, Suburban, Tahoe
 2015 GMC Canyon, Sierra, Yukon models
 Equipped with IO5, IO6, or UY4 Radio

This PI was superseded to update Warranty Information. Please discard PIC6085.

Condition/Concern

A customer may comment that they are unable to access XM Weather. During diagnosis, a technician may notice that the icon can be highlighted but they are unable to access/enter the XM Weather application.

Recommendation/Instructions

Reprogram the HMI via USB and SPS programming. Please refer to SI for Human Machine Interface Control Module Programming and Setup for "Reprogram Control Module".

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
2810345	SPS Programming	0.3
	Install Software with USB	0.3

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION