

A PDF of this newsletter and previous ones can be found by logging in to ServiceNet and clicking on the [Elsa Newsletter](#) section in the Technician References menu.

VW Elsa Newsletter



Das Auto.

Edition 131: April 13, 2015

Content

- [Technical Bulletins](#)
- [Pending Service Solutions](#)
- [Tech Tips](#)
- [Campaigns](#)
- [Updates](#)
- [Suggestions](#)



Technical Bulletins

01 15 08 - 2040171 Supersedes Technical Bulletin V01 1506 dated March 26, 2015 to include Golf SportWagen applicability.					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Passat, Jetta, Beetle, Beetle Convertible	2015	2.0L TDI (CVCA)	All	All	All
Golf, Golf SportWagen	2015	2.0L TDI (CRUA)	All	All	All
MIL ON Camshaft Position Faults P0011 and or P0016 Stored in Fault Memory (See Technical Bulletin for DTC Codes) Production Solution: Measures implemented into production.					

**24 15 03 - 2040179 Supersedes Technical Bulletin V241502 dated March 24, 2015 to include additional engine applicability.
DTC P2014 Intake Manifold Position Sensor -G336- Replacement**

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta, Beetle, Beetle Convertible	2013–2015	2.0T (CPPA, CPLA)	All	All	All
Jetta, Passat, Beetle, Beetle Convertible	2014–2015	1.8T (CPKA, CPRA)	All	All	All
GTI	2015	2.0T (CXCA, CXCB)	All	All	All
GTI	2015	2.0T (CNTA)	All	All	All
Golf	2015	1.8T (CNSB, CNSA)	All	All	All
Golf, Golf SportWagen	2015	1.8T (CXBA, CXBB)	All	All	All

Direction on proper part replacement when diagnosing fault code P2014 in the ECM.

Production Solution: Information only.

66 15 03 - 2040233 PDI - Front License Plate Bracket - Installation Instructions

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Golf-R	2015	2.0L (CYFB)	All	All	All

Vehicles not delivered with a **front** license plate bracket.
For states that require a front license plate, please use this document as a reference.

Production Solution: No production change required.

66 15 04 - 2040233 Supersedes Technical Bulletin V661503 to include part number color code.

PDI - Front License Plate Bracket - Installation Instructions

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Golf-R	2015	2.0L (CYFB)	All	All	All

Vehicles not delivered with a front license plate bracket.
For states that require a front license plate, please use this document as a reference.

Production Solution: No production change required.

Pending Service Solutions

No new Pending Service Solutions this week.

[Back to top](#)

Tech Tips

No new Tech Tips this week.

Campaigns

2306 - Clean Diesel Engine ECM Software Update					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Beetle, Beetle Convertible, Jetta, Golf, Jetta SportWagen/Golf Wagon	2010–2014	2.0L TDI®	All	See Campaign/Action screen in Elsa	See Campaign/Action screen in Elsa
<p>The vehicle's engine management software has been improved to assure the vehicle's tailpipe emissions are optimized and operating efficiently. Under certain operating conditions, the earlier strategy may have increased the chance of the vehicle's MIL light illuminating. If the MIL illuminates for any reason, the vehicle will not pass an IM emissions inspection in some regions.</p>					

REVISION: 42G8 - Rear Axle Trailing Arm Inlay Installation

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta	2011–2013	All	All	See Campaign/Action screen in Elsa	See Campaign/Action screen in Elsa
Beetle	2012–2013	All	All	See Campaign/Action screen in Elsa	See Campaign/Action screen in Elsa

Revision Summary

Additional steps added to the repair procedure.

If an affected vehicle had sustained damage to rear axle components (from a rear or side-rear impact crash or after striking a high road obstacle while driving in reverse at higher speed) and a repair facility did not correctly diagnose/repair rear axle trailing arm damage, the durability of the trailing arm(s) could be reduced. This can lead to a sudden fracture of the trailing arm, a loss of vehicle control, and a crash without warning.

This recall does not address a vehicle design or manufacturing defect; rather, the potential for this defect to be present can only occur *after* an affected vehicle has sustained damage to rear axle components as described above, and only if the damage is not properly repaired.

Updates

No new updates this week.

Suggestions

Please send comments or suggestions to: vwoa.workshopinformation@vw.com

[Back to top](#)

© 2015 Volkswagen of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.