

A PDF of this newsletter and previous ones can be found by logging in to ServiceNet and clicking on the [Elsa Newsletter](#) section in the Technician References menu.



Audi Elsa Newsletter

Edition 143: July 6, 2015

Content

- [Technical Bulletins](#)
- [Pending Service Solutions](#)
- [Campaigns](#)
- [Updates](#)
- [Suggestions](#)



Technical Bulletins

23 MIL on, no start or rough running (DTCs P0087, P0088, P0191) (2040752/1)

Model(s)	Year	Vehicle Specific Equipment
Q7	2009-2012	TDI clean diesel
A3	2010-2012	TDI clean diesel

Condition:

- MIL on.
- Vehicle either runs roughly or does not start.
- One or more of the following DTCs is stored in the engine control module (ECM), J623 (address word 01):
 - DTC P0087 (Fuel rail/system pressure - too low)

- DTC P0088 (Fuel rail/system pressure - too high)
- DTC P0191 (Fuel rail pressure sensor “A” circuit range/performance)

Production Solution: Not applicable.

91 MIB MMI: Traffic incidents are not prioritized by proximity to vehicle (2040843/1)

Model(s)	Year	Vehicle Specific Equipment
A3	2015–2017	MIB navigation
A6, A7	2016–2017	MIB-2 navigation

Condition: One of the following conditions related to the traffic display in the MIB MMI is present:

- Traffic incidents nearest to the vehicle are not shown first.
- Traffic incidents in the surrounding area do not appear to be listed.

Production Solution: Not applicable.

96 Radio station or media track information does not shown in cluster DIS - Gen 3 Concert Radio (2034733/2)

Model(s)	Year	Vehicle Specific Equipment
A4, A5, A5 Cabriolet, Q5	2013–2016	Not Applicable

Condition: The customer complains that after the vehicle is started, the name of the current radio station or media track is not shown in the driver information system (DIS). After the music input is changed to a different source and then changed back (i.e., media to radio to media or radio to media to radio), the radio station or media track information is shown in the DIS.

Production Solution: Not applicable.

[Back to top](#)

**87 Unpleasant odor from heating and ventilation system
(2010146/13)**

Model(s)	Year	Vehicle Specific Equipment
All	2005–2017	Not Applicable
<p align="center">Condition:</p> <ul style="list-style-type: none"> • There is an unpleasant, musty odor coming from the heating and ventilation system. • The odor usually occurs when the vehicle has been sitting unused for five hours or more. • The odor usually occurs within 20 to 60 seconds after the vehicle is started. <p align="center">Production Solution: Not applicable.</p>		

19 Coolant pipe seepage on turbocharger (2036167/2)

Model(s)	Year	Vehicle Specific Equipment
S6, S7, A8, S8	2013	4.0T
<p align="center">Condition:</p> <ul style="list-style-type: none"> • The low coolant level light is illuminated. <ul style="list-style-type: none"> • The coolant level is too low. • A black crust is visible on the turbocharger coolant lines. <p>Production Solution: Modified coolant feed pipes, coolant return pipes, and o-rings.</p>		

**91 MIB MMI navigation database not enabled (B126CF2)
(2041043/1)**

Model(s)	Year	Vehicle Specific Equipment
A3, A3 Cabriolet	2015–2016	PR 7UG
<p align="center">Condition:</p> <ul style="list-style-type: none"> • The navigation function is not available, and the message “The navigation data are not activated” appears in the MMI. 		

- DTC B126CF2 (Navigation system navigation database not enabled) is set in the information electronics control module, J794 (address word 5F).

Production Solution: Not applicable.

**23 MIL on, no start or rough running (DTCs P0087, P0088, P0191)
(2040752/2)**

Model(s)	Year	Vehicle Specific Equipment
Q7	2009–2012	TDI clean diesel
A3	2010–2012	TDI clean diesel

Condition:

- MIL on.
- Vehicle either runs roughly or does not start.
- One or more of the following DTCs is stored in the engine control module (ECM), J623 (address word 01):
 - DTC P0087 (Fuel rail/system pressure - too low)
 - DTC P0088 (Fuel rail/system pressure - too high)
 - DTC P0191 (Fuel rail pressure sensor “A” circuit range/performance)

Production Solution: Not applicable.

Pending Service Solutions

No new Pending Service Solutions this week.

Campaigns

No new campaigns this week.

Updates

No new updates this week

Suggestions

Please send comments or suggestions to: aoa.workshopinformation@audi.com

[Back to top](#)

© 2015 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.