



No.: 15 CSA-29
December 18, 2015

TO: Service Locations

FROM: Service Systems Development

SUBJECT: **Release of DiagnosticLink® 8.03 Service Pack 1**

SUBJECT DETAIL

On Monday, January 11, 2016, Service Pack (SP) 1 for DiagnosticLink® 8.03 Standard and Professional will be available for download from the Detroit Diesel server. This service pack will support the following:

- Fix the ADS pump speed instrument issue where incorrect values were reported
- Fix issue in Actions panel where TCNG/TCM Transmission Type couldn't be set
- Additional Advanced Diagnostics

IMPORTANT NOTE: You must have DiagnosticLink 8.03 Standard or Professional to receive Service Pack (SP) 1.

DiagnosticLink 8.0, DiagnosticLink 8.01, and DiagnosticLink 8.02 will not receive this service pack.

In November of 2015, the DiagnosticLink 8.03 software tool was released to our service network. In order to maintain access to the Detroit Diesel server data, all Master Reprogramming Stations must be kept updated with the current version of DiagnosticLink software to avoid any interruptions.


Please refer to [15 CSA-25](#) for ordering information and instructions.

UPDATE INSTRUCTIONS

NOTE: You must have DiagnosticLink 8.03 installed on your computer prior to applying this patch.

SP1 will automatically be downloaded when you connect to the DDC server. Please do the following:

1. Open DiagnosticLink software.
2. From the Tools drop-down menu, select Update.



3. A screen will be displayed showing the progress of the download. Follow the installation prompts to complete the download.
4. Verify that the patch has been applied by selecting **About** from the **Help** dropdown menu. Verify the following:

Application Components
DiagnosticLink **08.03SP1-xxxxx-xxxxx**

CONTACT INFORMATION

Please contact the Detroit Customer Support Center at 800-445-1980 or email csc.software@daimler.com if you have any questions.