



No.: 15 TS-16Rev1
December 2, 2015

TO: Service Locations

FROM: Service Systems Development

SUBJECT: **EPA10 Reman MCM Improvement for Fault Codes SPN 651 to 656**

ISSUE

EPA10 Vehicles have experienced a high volume of injector circuit faults. The fault codes involved are the following;

- SPN 651/FMI 3 and 4
- SPN 652/FMI 3 and 4
- SPN 653/FMI 3 and 4
- SPN 654/FMI 3 and 4
- SPN 655/FMI 3 and 4
- SPN 656/FMI 3 and 4

Reman has developed an improved MCM to reduce faults for the above injector circuit codes. The improved Reman MCM 2.0 has been released with the unique part number: RA0014469935.

REQUIRED ACTION

PSL troubleshooting has been updated for EPA10 only. Refer to, and follow the appropriate troubleshooting procedures in PSL. MCM 2.1 for GHG 14 already has this improvement incorporated.

CLAIM INFORMATION

Normal in-warranty procedures apply. When injector resistance values lead to the MCM replacement, the correct Primary Failed Part is the injector but the replacement part is the MCM.

CONTACT INFORMATION

Please contact the Detroit® Customer Support Center at 800-445-1980 or email csc@daimler.com if you have any questions.