

FRONT TUBE CAP Prevost vehicles

DESCRIPTION

On the vehicles affected by this bulletin, add caps on openings at front structure bottom corners.

MODEL YEAR(S) AND VEHICLES INVOLVED

NOTICE TO SERVICE CENTERS	
Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.	
Model	VIN
X3-45 Commuter Model Year : 2015	From 4RKG33499F9737002 up to 4RKG33498F9737024 incl.
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.	

MATERIAL NEEDED

Order the following parts:

Part No.	Description	Qty
508394	CAP, SQUARE END 1.5 X 1.5	2

NOTE
Material can be obtained through regular channels.

PROCEDURE

 DANGER
Park vehicle safely, apply parking brake, stop engine. In the battery box, set the battery cut-off switch to the OFF position prior to working on the vehicle.

- 1) At the bottom of vertical members on the front structure bottom corner, add cap #508394 (Fig. 1)
- 2) If cap does not have ribs (Fig. 2) ,glue with Simson ISR 70-03 Black Glue.



Figure 1




Figure 2

Date	Expiration	Release	Page
04.2015	04.2017	1	3(3)

PARTS / WASTE DISPOSAL

Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

ESTIMATED TIME

The time required to perform this special bulletin is approximately 30 minutes.

OTHER

VBC Bulletin	N/A
Fail Code	18.00
Defect Code	09
System Condition	B
Causal Part	479565

Prevost engages in a continuous program of testing and evaluating to provide the best possible product. Prevost, however, is not committed to, or liable for updating existing products.