

Date	Expiration	Release	Page
05.2015	05.2017	0	1(3)

Release 0: Original release

HALDEX CONSEP VOLTAGE
Prevost vehicles

DESCRIPTION

On the vehicles affected by this bulletin, the voltage rating of the condenser / separator coil may be inappropriate for our application. Our application is 24V.

MODEL YEAR(S) AND VEHICLES INVOLVED

NOTICE TO SERVICE CENTERS	
Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.	
Model	VIN
X3-45 Commuter Model Year : 2015	The following individual vehicles: 4RKG33492F9737049; 4RKG33499F9737050 4RKG33490F9737051; 4RKG33492F9737052 4RKG33494F9737053; 4RKG33496F9737054 4RKG33498F9737055; 4RKG3349XF9737056 4RKG33491F9737057; 4RKG33493F9737058 4RKG33495F9737059; 4RKG33491F9737060
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.	

MATERIAL NEEDED

Order the following parts if required:

Part No.	Description	Qty
649940	OIL SEPARATOR / CONSEP CONDENSER 1/2" NPT	1

NOTE

Material can be obtained through regular channels.

Date	Expiration	Release	Page
05.2015	05.2017	0	2(3)


PROCEDURE



DANGER

Park vehicle safely, apply parking brake, stop engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.

- 1) Inspect the identification plate on the Haldex condenser – separator.
- 2) If the ID plate indicates 12 VDC, replace with a new part #649940. Make sure the new part is rated 24 VDC.



PARTS / WASTE DISPOSAL

Return replaced parts to Prevost with A.F.A. for full reimbursement.

ESTIMATED TIME

The time required to perform this special bulletin is approximately 15 minutes for inspection only **or** 45 minutes for the complete procedure.

Date	Expiration	Release	Page
05.2015	05.2017	0	3(3)

OTHER

VBC Bulletin	N/A
Fail Code	12.00
Defect Code	09
System Condition	B
Causal Part	649940

Prevost engages in a continuous program of testing and evaluating to provide the best possible product. Prevost, however, is not committed to, or liable for updating existing products.