

Special Bulletin

SP15-331A

Date	Expiration	Release	Page
07.2015	07.2017	2	1(4)

Rev A : This revision replaces previous versions

September 18, 2015 Added instructions to apply pressure to the decal with a plastic tool.

AUXILIARY EQUIPMENT DECAL REPLACEMENT

Prevost vehicles

DESCRIPTION

On the vehicles affected by this bulletin, replace the two auxiliary equipment decals in the first two road side parcel rack compartments.

MODEL YEAR(S) AND VEHICLES INVOLVED

NOTICE TO SERVICE CENTERS	
Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.	
Model	VIN
X3-45 Commuter Model Year : 2014, 2015	The following individual vehicles: 2PCG33495 <u>E</u> C73 <u>5590</u> , 2PCG33498 <u>E</u> C73 <u>5602</u> , 4RKG33499 <u>F</u> 973 <u>7081</u> And from 4RKG33497 <u>F</u> 973 <u>7001</u> up to 4RKG33494 <u>F</u> 973 <u>7067</u> incl.
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery. The owners of the vehicles affected by this bulletin will be advised by a letter indicating the Vehicle Identification Number (VIN) of each vehicle concerned.	

MATERIAL NEEDED

Order the following parts:

Part No.	Description	Qty
069442	Decal, Audio Rack	1
069443	Decal, Second Parcel Rack	1

NOTE

Material can be obtained through regular channels.

PROCEDURE

Date	Expiration	Release	Page
07.2015	07.2017	2	2(4)



DANGER

Park vehicle safely, apply parking brake, stop engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.

- 1) Locate the road side parcel rack compartment.(Fig. 1)




Figure 1

Date	Expiration	Release	Page
07.2015	07.2017	2	3(4)

- 2) Remove cable seal. Open the compartment. The decals are located on the inside looking into the compartment.
- 3) Replace decals 069442 for the audio equipment and 069443 the auxiliary equipment. (Fig. 1)
Apply pressure on the decal with a wide plastic spatula or equivalent tool.




Figure 2

- 4) Install a new cable seal.

PARTS / WASTE DISPOSAL

Discard waste according to applicable environmental regulations (Municipal/State[Prov.]/ Federal)

ESTIMATED TIME

The time required to perform this special bulletin is approximately half an hour.

OTHER

Special Bulletin

SP15-331A

Date	Expiration	Release	Page
07.2015	07.2017	2	4(4)

VBC Bulletin	N/A
Fail Code	18.02
Defect Code	09
System Condition	B
Causal Part	069442

Prevost engages in a continuous program of testing and evaluating to provide the best possible product. Prevost, however, is not committed to, or liable for updating existing products.