

Tech Tip T-TT-0324-15

March 18, 2015

P3190/P3191/P3193/P0A0F Engine No Start/Poor Engine Power After Inverter Service or Replacement

Market USA

Service Calegory

Engine/Hybrid System

Engine Control

Highlander HV

			_	-		COMPAND)
	4 1 4	1.14				LES
w	2.11.2	4 24 80	97 1 2		 3 I K PH	

2006-2012

Highlander HV

CONDITION

Engine No Start and/or Poor Engine Power DTCs set immediately after performing service on the Inverter such as SSC D0M for IPM replacement or Inverter Assembly installation.

RECOMMENDATIONS

All intake system components such as air filter, air cleaner housing, resonators, air induction hoses and ducts MUST be installed before attempting Ready On or engine performance DTCs may occur.

LINK REFERENCES

This Tech Tip does not contain any link references

Expires on

03/18/2016

© 2015, Toyota Motor Sales, USA

Page 1 of 1

Ver 2 5 02/08/2015 T