

Bulletin No.: PI1445

Date: Mar-2015

PRELIMINARY INFORMATION

Subject: Malfunction Indication Lamp (MIL) On, P2227 DTC Set

Models: 2013-2015 Buick LaCrosse

2013-2015 Cadillac XTS 2013 Chevrolet Impala

2013-2015 Chevrolet Camaro

2014-2015 Chevrolet Impala (VIN 1)

Equipped with 3.6L Engine (RPOs LF3, LFX)

Attention: This PI also applies to any of the above models that may be Export vehicles.

Condition/Concern

Some customers may comment on a malfunction indicator lamp (MIL) on. Technicians may find DTC P2227 set current or in history.

This may be caused by a software anomaly.

Recommendation/Instructions

Important: DO NOT replace the mass air flow sensor for this condition.

Engineering is aware of this condition and is working on a resolution. Once a solution becomes available, this PI will be updated. In the meantime, the technicial can clear the code.

Customer Information

Please communicate to the customer that we apologize for this inconvenience and that General Motors is working on a solution for this concern. Once a solution is available, this PI will be updated with additional details - allowing dealership personnel to contact the customer to schedule a service appointment and repair the vehicle.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safety. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION