

Reception interference in radio mode

Topic number	LI54.65-P-060694
Version	1
Design group	54.65 Parking assist
Date	01-26-2015
Validity	Model 246 with code 218 in the VIN range from J278334 to J288517 Model 242 with code 218 in the VIN range from J001965 to J002745
Reason for change	
Reason for block	

Complaint:

Reception interference may occur in radio mode at vehicle speeds up to 30 km/h.

Cause:

EMC interference from the reversing camera.

Remedy:

Update software of reversing camera using Xentry DVD 10/2014 or higher.

Symptoms
Communication/information / Entertainment / Radio / Poor reception
Communication/information / Entertainment / Video TV/DVD / Poor reception
Communication/information / Entertainment / Audio / Speakers emit interference noise
Communication/information / Entertainment / Audio / Poor audio quality
Communication/information / Entertainment / Digital radio/Satellite digital audio radio / Sound interruption in digital mode

Work units				
Op. no.	Operation text	Time	Damage code	Note
			87001 90	

Validity		
Vehicle	Engine	Transmission
B (242, 246)	*	*

Full model designation breakdown		
Vehicle	Engine	Transmission
242.848	270.920	711.632
242.848	270.920	724.003
242.890	000.000	000.000
242.890	780.990	000.000
246.200	651.901	711.642
246.200	651.901	724.003
246.201	651.901	711.642
246.201	651.901	724.003
246.202	651.930	724.011
246.203	651.930	724.003
246.205	651.930	724.011
246.207	651.930	711.645
246.207	651.930	724.003
246.208	651.930	711.645
246.208	651.930	724.003
246.211	607.951	711.632
246.211	607.951	724.020
246.212	607.951	711.632
246.212	607.951	711.645
246.212	607.951	724.020
246.242	270.910	711.632
246.242	270.910	711.643
246.242	270.910	724.002
246.243	270.910	711.643
246.243	270.910	724.002
246.243	270.910	724.003
246.244	270.920	724.003
246.246	270.920	724.011
246.247	270.920	724.011