

Uncomfortable 2-3 shift in MODEL 205 with TRANSMISSION 722.9 and ENGINE 274

Topic number	LI27.00-P-059608
Version	4
Design group	27.00 General
Date	03-23-2015
Validity	MODEL 205 with TRANSMISSION 722.9 and ENGINE 274
Reason for change	Cause and remedy adjusted
Reason for block	

Complaint:

Under certain preconditions the 2-3 upshift can be uncomfortable.

Cause:

Software application of VGS software A 000 902 68 24.

Remedy:

Do not perform any repairs on the transmission. Repairs will not rectify the complaint. This LI will be updated when a remedy is available.

If complaints are received concerning shifts other than that given in the description, please follow normal 722.9 diagnostic routine. If complaint is not resolved, please create a PTSS case and attach the current quick test report with fault freeze frame data and the current EEPROM data of the VGS4NAG2 as a logfile (*.log).

Symptoms

Power transmission / Automatic transmission / Automatic transmission - function / Shifts

Work units

Op. no.	Operation text	Time	Damage code	Note
			27013 45	Automatic transmission/dual clutch transmission 2-3 shift operation shifts hard

Validity

Vehicle	Engine	Transmission
205.040	274	722.995
205.042	274	722.995

205.045	274	722.995
205.048	274	722.994
205.049	274	722.969
205.140	274	722.995
205.142	274	722.995
205.145	274	722.995
205.240	274	722.995
205.242	274	722.995
205.245	274	722.995