

Message in instrument cluster "Measurement of engine oil level not possible"

Topic number	LI54.21-P-061171
Version	1
Design group	54.21 Control modules/modules
Date	03-30-2015
Validity	190.377/378
Reason for change	
Reason for block	

Complaint:

Message in instrument cluster "Measurement of engine oil level not possible"

Cause:

Powertrain control unit (PTCU) software release

Remedy:

Update powertrain control unit (PTCU) using the add-ons listed below.

Note:

Software available with

- Add-on 4348 (Xentry version 12/2014)
- Add-on 4349 (Xentry version 03/2015)

Symptoms
Power generation / Engine lubrication/oil cooling / Engine lubrication/oil cooling indicator lamp / Engine oil level indicator lamp / lit
Communication/information / Information display / Displays / Multifunction display / Multifunction display, error messages / Due to faulty reporting system
Power generation / Engine lubrication/oil cooling / Engine lubrication/oil cooling display message / Oil sensor message
Communication/information / Information display / Displays / Multifunction display / Multifunction display, error messages / Drivetrain - Malfunction (white warning message)

Work units				
Op. no.	Operation text	Time	Damage code	Note
			5440Z 90	

Validity		
Vehicle	Engine	Transmission
190.377	*	*
190.378	*	*