

Service Campaign Bulletin



Mercedes-Benz

Campaign No. 2015030007, March 2015

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model 117, Model Year 2015**
Update Transmission Control Module Software

This Service Campaign has been initiated because Daimler AG (DAG), the manufacturer of Mercedes-Benz vehicles, has determined that the transmission control module software does not correspond to current series production. To ensure proper function of the transmission an authorized Mercedes-Benz dealer will update the transmission control module software at the next workshop visit.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately 6 vehicles are affected.

Order No. P-SC-2015030007

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Service Campaign Bulletin

Service Campaign Bulletin


Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

Procedure

Note:

- Use DAS/Xentry 12/2014-01-02/2015 with add-on 4160 or higher.
 - Follow the steps exactly as described in DAS/Xentry.
 - Connect battery charger (battery voltage  >12.5V).
 - Ensure all electrical consumers are switched-off.
 - In the event of software/SCN update issues, contact Star Diagnosis User Help Desk. Please refer to the “pre-call” check list before contacting UHD
 - Refer to Star Diagnosis System (SDS) Best Practices Guide.
1. Update fully integrated transmission control module software:
Quick test view / DCT [DKG] / Electronic transmission control for dual clutch transmission (Y3/14n4) / Adaptations / Control unit programming.
 2. Follow on-screen instructions.

Note:

The following allowable labor operation should be used when submitting a warranty claim for this repair:

Warranty Information

Operation: Connect/disconnect battery charger (02-5058)
Star Diagnosis System (SDS), Connect/disconnect (02-4762)
Update fully integrated transmission control module software (02-8841)

Damage Code	Operation Number	Labor Time (hrs.)
54 955 45 8	02-5058	0.1
	02-4762	0.1
	02-8841	0.1

Note

Operation Number labor times are subject to change.