

# Service Campaign Bulletin



Mercedes-Benz

Campaign No. 2015030002, March 2015

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model 217 (CL-Class) Model Year 2015, Model 222 (S-Class),  
Model Years 2014-2015  
Update Transmission and Engine Control Module Software**

This Service Campaign has been initiated because Daimler AG (DAG), the manufacturer of Mercedes-Benz vehicles, has determined that the software in the Engine and Transmission Control Modules may not meet current production configuration. To correct this condition an authorized Mercedes-Benz dealer will update the Engine and Transmission Control Module software at the next dealer visit.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately 2,411 vehicles are affected.

Order No. P-SC- 2015030002

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Service Campaign Bulletin

Service Campaign Bulletin


Service Campaign Bulletin

Service Campaign Bulletin

Service Campaign Bulletin

## Procedure

### Note:

- Use DAS/Xentry 12/2014-01-02/2015 with all associated patches or higher.
  - Follow the steps exactly as described in DAS/Xentry.
  - Connect battery charger (battery voltage  >12.5V).
  - Ensure all electrical consumers are switched-off.
  - In the event of software/SCN update issues, contact Star Diagnosis User Help Desk. Please refer to the “pre-call” check list before contacting UHD
  - Refer to Star Diagnosis System (SDS) Best Practices Guide.
1. Update software for fully integrated transmission control module:  
Control units view / Drive Type / VGS-transmission control / Adaptations / Control unit programming then follow on-screen instructions.
  2. Update software for engine control module:  
Control unit view / Drive type / ME-SFI motor electronics / Adaptations / Control unit programming then follow on-screen instructions.
  3. Carry out transmission adaptation.

### Note:

The following allowable labor operation should be used when submitting a warranty claim for this repair:

## Warranty Information

**Operation:** Connect/disconnect battery charger (02-5058)  
Star Diagnosis System (SDS), Connect/disconnect (02-4762)  
Update software for fully integrated transmission control unit and engine control unit (02-8820)  
Perform transmission adaptation test drive (02-8851).

Damage Code	Operation Number	Labor Time (hrs.)
54 983 42 8	02-5058	0.1
	02-4762	0.1
	02-8820	0.3
	02-8851	ZM

### Note

Operation Number labor times are subject to change.