

B-pillar trim in model series 117 chafed through

Topic number	LI68.30-P-059216
Version	4
Design group	68.30 Coverings, trim
Date	06-30-2015
Validity	Model series 117 up to VIN end number 204196
Reason for change	Validity end VIN number added
Reason for block	

Complaint:

The B-pillar trim in model series 117 is chafed through at the height of the belt outlet.

Attachments	
File	Description
CLA 001.jpg	Complaint
CLA 002.jpg	Complaint
CLA 004.jpg	Complaint
CLA 008.jpg	Complaint
CLA 009.jpg	Complaint

Cause:

Due to its design, the seat belt can chafe through the B-pillar trim.

Remedy:

Replacement of B-pillar trim with updated parts.

Symptoms
Body / Interior equipment / Interior trim / Deformed
Body / Interior equipment / Interior trim / Bad fitting
Body / Interior equipment / Interior trim / Pressure mark

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 117 690 23 00			Left B-pillar trim	1	Please observe color code	X
A 117 690 24 00			Right B-pillar trim	1	Please observe color code	X

Validity		
Vehicle	Engine	Transmission

117.301	*	*
117.302	*	*
117.303	*	*
117.305	*	*
117.308	*	*
117.312	*	*
117.342	*	*
117.343	*	*
117.344	*	*
117.345	*	*
117.346	*	*
117.347	*	*
117.352	*	*

Attachments

CLA 001.jpg:



CLA 002.jpg:



CLA 004.jpg:



CLA 008.jpg:



CLA 009.jpg:

