



Service Bulletin

INFORMATION

Subject: Component Replacement Necessary After Engine Replacement

Models: 2006-2013 Corvette
Equipped with Engine RPOs LS3, LS7, LS9

Attention: This Bulletin also applies to any of the above models that may be Export vehicles.

This Bulletin has been revised to remove RPO references in Models and remove the flushing information and provide replacement information. Please discard Corporate Bulletin Number 06-06-01-024A.

Engine Replacement – Oiling System Debris

Notice: Debris in the remote oil tank and oiling system may be pulled back into the motor causing severe engine damage.

If replacement of the engine becomes necessary, or any failure is experienced that may cause debris to enter the oil supply, the remote oil tank must be replaced. Additionally, the intake manifold, PCV, PCV Lines, oil cooler and both oil cooler lines should be replaced.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION