



Service Bulletin

PRELIMINARY INFORMATION

Subject: Driver Information Center (DIC) Buttons Disabled When Fill Fuel Warning Message is Displayed

Models: 2015 Chevrolet Spark

Condition/Concern

Some customers may comment on the DIC button doesn't function and when this occurs the fill fuel warning message is displayed.

This is normal functionality to remind the driver that the vehicle is low on fuel.

Recommendation/Instructions

Refuel the vehicle and the buttons will function properly. Refer to Driver Information Center (DIC) in the owners manual.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION