



Service Bulletin

PRELIMINARY INFORMATION

Subject: Low Tire Pressure Indicator Illuminated and/or Slow Loss of Tire Pressure

Models: 2014 Cadillac XTS

Equipped with 19x8.5 Aluminum Wheel (RPO RT9) and Built Before November 1, 2013

This PI replaces PIE0333A. Please discard PIE0333A.

Condition/Concern

Some customers may comment on an illuminated low tire pressure indicator and/or the tire(s) slowly loses air pressure over a period of time.

Recommendation/Instructions

If you encounter a vehicle with the above concern, replace the affected tire.

If patterning on the bead seat or seat shows corrosion, they should address it using the process outlined in the latest version of Bulletin 08-03-10-006.

Important: The wheel should not be replaced unless corrosion exceeds guidelines shown in the latest version of Bulletin 08-03-10-006.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
8060440	Goodyear/Dunlop Tire Replacement	Use Published Labor Operation Time

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION