



Service Bulletin

PRELIMINARY INFORMATION

Subject: Information on Anti-Abrasion Tape Located on Underside of Rear Liftgate or Rear Compartment Lid

Models: 2016 Chevrolet Corvette


Attention: This PI also applies to any of the above models that may be Export vehicles.

Condition/Concern


Some customers or technicians during Pre-Delivery Inspection (PDI) may notice a strip of black anti-abrasion tape attached to the underside of the rear liftgate or rear compartment lid.

Locations of Anti-Abrasion Tape

Convertible Anti-Abrasion Tape Locations



Coupe Anti-Abrasion Tape Locations



Recommendation/Instructions

Important: DO NOT REMOVE THE ANTI-ABRASION TAPE.

The black tape attached to the underside of the liftgate/rear compartment lid is an anti-abrasion tape used to improve the power release function.

If the tape is removed, the liftgate/rear compartment lid may not release high enough from the rear weatherstrip, causing difficulty opening.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION