



Service Bulletin

PRELIMINARY INFORMATION

Subject: Tire Pressure Monitor (TPM) Concerns After Accessory Wheel Installation

Models: 2010-2015 GM Passenger Cars and Light Duty Trucks with Accessory Wheels

Attention: This PI also applies to any of the above models that may be Export vehicles.

Condition/Concern

Some customers may comment that the tire pressure monitor (TPM) indicator is active on the cluster.

This may be caused by the TPM sensors not being re-learned after the installation of accessory wheels.

Recommendation/Instructions

The TPM sensors must always be re-learned when accessory wheels are installed on the vehicle.

Note: Installation time includes the time to re-learn the TPM sensors and this should be completed during the accessory installation. If the TPMs were not re-learned at installation, this should not be charged to warranty.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION