

Service Bulletin

PRELIMINARY INFORMATION

Subject: SES Light Comes On

Models: 2015 Chevrolet Colorado 2015 GMC Canyon Equipped with HFV6 3.6L LFX Engine

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

SES/MIL on with P0326 or P0331 set in history.

Recommendation/Instructions

If you get a vehicle in with a P0326 (Knock Sensor Performance Bank 1) or P0331 (Knock Sensor Performance Bank 2) set in HISTORY only, check for loose connection at the sensor and check connections at the ECM.

Note: IF there are poor connections, Noise, or a current code, this PI DOES NOT apply and you should continue with normal SI diagnostics.

If no connection concerns are found, at this time, DO NOT replace the knock sensor or the ECM for this code.

Engineering has identified a concern causing this code and is working to release a repair.

When the repair is available this PI will be updated accordingly.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION