



Service Bulletin

PRELIMINARY INFORMATION

Subject: SES Lamp P0521 Setting In Cold Ambient Temperatures

Models: 2007-2013 Cadillac CTS-V, Escalade
2007-2013 Chevrolet Avalanche, Camaro SS, Colorado, Corvette, Express, Silverado, Suburban, Tahoe
2007-2013 GMC Canyon, Sierra, Savana, Yukon
with a V8 Engine (RPOs L20, L77, L94, L96, L99, L9H, LC8, LC9, LH9, LMF, LMG, LY6, LZ1)

This PI was superseded to update Recommendation/Instructions. Please discard PIP5276.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

A concern of a P0521 setting on a cold start with the outside temp below 0 degrees F.

Recommendation/Instructions

If you get a Gen4 V8 with DTC P0521 setting in cold weather and it has a PF48E oil filter, change the filter to a PF48 if one is available.

If a PF48 cannot be found use a new PF48E. (This PI will be up dated with new information as it comes in.)

This is only for situations where the ambient temperature is -5 degrees or less.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
4065530	Oil Filter Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION