



Service Bulletin

PRELIMINARY INFORMATION

Subject: Loose Battery Cover Or Missing Battery Cover Latch In Rear (Trunk) Compartment

Models: 2013 - 2015 Cadillac ATS

This PI was superseded to update Warranty Information. Please discard PIC5754A.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

The battery cover latch may have become separated from the cover plate allowing the cover to fit loosely on the trunk rear compartment side trim.

Recommendation/Instructions

Important: Do NOT replace the rear compartment side trim for this condition.

Replace the battery cover assembly. This cover is now available separately through GM CCA.

Parts Information

Part Number	Description	Qty
23202299	COVER,R/CMPT SI T/PNL ACC HOLE	1

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
1046520	Rear Compartment Side Trim Panel Stowage Compartment Cover Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION