Service Bulletin

Bulletin No.: PIP5278

Date: Mar-2015

PRELIMINARY INFORMATION

Subject: Transmission Fluid Leak Out the Vent

Models: 2015 Chevrolet Corvette

Equipped with 8L90 Automatic Transmission (RPO M5U)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Transmission fluid leaking from the transmission vent may be noted on new cars coming off of the transport truck

Recommendation/Instructions

If a fluid leak from the transmission vent is found please contact TAC.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safety. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

