



Service Bulletin

PRELIMINARY INFORMATION

Subject: PQC Parts Restriction On 2014 and 2015 Chevrolet Camaro Equipped With RPO Z28 Only

Models: 2014 and 2015 Chevrolet Camaro equipped with RPO Z28

This PI was superseded to update Recommendation/Instructions. Please discard PIC5983D.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

The parts listed below for the Z28 equipped 2014 and 2015 Chevrolet Camaro have been placed on a PQC parts restriction.

Recommendation/Instructions

Please contact PQC at (866)654-7654, if you require the following parts for a 2014 or 2015 Chevrolet Camaro equipped with RPO Z28

Important: Dealers cannot order this part for stocking their inventory.

Note: Please do not to contact PARTECH or SPAC at this time for the 2014 and 2015 Chevrolet Camaro Z28 PQC Restricted Parts

Q1: Is the vehicle a 2014 or 2015 Chevrolet Camaro equipped with RPO Z28

[If no, The parts listed below are available only for the 2014 and 2015 Chevrolet Camaro equipped with RPO Z28]

If yes, please be prepared to provide the Following information

- Warranty Repair Order or Customer Pay Parts Counter Sales Ticket Number
- The VIN of the 2014 or 2015 Chevrolet Camaro equipped with RPO Z28
- Customer's last name

The above information is also required for customer pay, or with TAC/DMA approval.

Restricted Part Numbers:

22958646 ROTOR-FRT BRK
22958647 ROTOR-RR BRK
22958658 CALIPER ASM-FRT BRK
22958607 CALIPER ASM-FRT BRK
22958637 CALIPER ASM-RR BRK
22958634 CALIPER ASM-RR BRK
22903660 STRUT ASM-FRT SUSP (W/ SPR)
22903659 STRUT ASM-FRT SUSP (W/ SPR)
23179350 MOLDING ASM-RKR PNL
23179351 MOLDING ASM-RKR PNL
23487228 SCOOP ASM-HOOD AIR
22968220 ESCUTCHEON – FRT GRL EMB
23468210 EMBLEM – FRT GRILL (Flow Tie)

22954889 WHEEL ASM-STRG
22873225 WHEEL-FRT
22873227 WHEEL-RR
23240634 FLARE ASM-F/FDR
23240635 FLARE ASM-F/FDR
23240650 FLARE ASM-RR WHL OPG
23240651 FLARE ASM-RR WHL OPG
22908036 EMBLEM ASM – E/Gate
22908498 EMBLEM ASM – FRT GRL
22894294 SEAT ASM-FRT
22894302 SEAT ASM-FRT
23473010 SHAFT ASM-RR WHL DRV
23473011 SHAFT ASM-RR WHL DRV
23468208 GRILLE – FRT UPR
22925211 PLATE – F/FDR VEH NA
22972716 COVER – D/SEAT BK
22972708 COVER – P/SEAT BK
23164563 CLEANER – AIR
12653293 SHIELD – INT MANIF SIGHT
12653294 SHIELD – INT MANIF SIGHT
23104737 SPOILER – F/END
22997723 FASCIA – FRT BPR
22985096 FASCIA – RR BPR LWR
22968219 COVER – FRT FOG LP OPG
22966600 COVER – A/CL HSG
23468209 PLATE – FRT GRL EMB BKG
23473511 ABSORBER ASM, RR SHK

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION