



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** E92 ECM PQC Restriction on Part Number 12662034 has ended.

**Models:** 2015 Chevrolet Tahoe, Suburban with V8 (L83, L86) gas engine  
2015 Chevrolet Colorado with LFX engine  
2015 GMC Yukon and Yukon XL with V8 (L83, L86) gas engine  
2015 GMC Canyon with LFX engine  
2015 Cadillac Escalade with V8 (L86) gas engine  
2015 Chevrolet Silverado/GMC Sierra with V6 (LV1, LV3) or V8 (L83, L86) gas engine  
2015 Chevrolet Corvette with LT1 engine  
2015 Cadillac XTS with LF3 engine  
2015 Cadillac CTS with LF3, LFX engine  
2015 Cadillac ATS with LFX engine

*This PI was superseded to update Part Restriction. Please discard PIP5223B.*

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

The E92 ECM PQC Restriction Part Number 12662034 has ended.

### Recommendation/Instructions

Parts can now be ordered through the regular CCA parts process.

GM Engineering would like to Thank all dealers that participated in this parts restriction.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

---

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION