



Service Bulletin

PRELIMINARY INFORMATION

Subject: Roof Antenna Missing from Trunk Kit During Pre-Delivery Inspection (PDI)

Models: 2015 Chevrolet Volt
Built Between VIN Breakpoint FU115573–FU117899

Condition/Concern

During Per-Delivery Inspection (PDI), some dealers may find that the roof antenna is missing from the trunk kit provided. This may be caused by improperly packaged trunk kits.

Recommendation/Instructions

If this condition exists, replace the missing antenna with part number 22969192. Refer to Radio Antenna Replacement in SI.

Parts Information

Part Number	Description
22969192	ANTENNA ASM-RDO

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description
0580128*	Replace Missing Radio Antenna During PDI

*This is a unique Labor Operation for Bulletin use to cover part cost only. The required labor is included in 0590072 Pre-Delivery Inspection.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION