2014	Tribeca	Body	

Tribeca

Tribeca

Tribeca

2013	Legacy & Outback	Transmission	CVT(diag)-39-42,77-84	Diagnostic steps changed for DTC's P0716, 2746 & 2750
2012	Legacy & Outback	Chassis	VDC(diag)-44,45	Diagnostic steps changed for DTC C0028.
2011	Legacy & Outback	Chassis	VDC(diag)-44,45	Diagnostic steps changed for DTC C0028.
2010	Legacy & Outback	Chassis	VDC(diag)-44,45	Diagnostic steps changed for DTC C0028.
2007	Legacy & Outback	Body	CC(diag)-16	Diagnostic steps changed for DTC 11.
2014	Tribeca	Body	LAN System (diag)-71	Diagnostic steps changed for DTC U1302.

LAN System (diag)-71

LAN System (diag)-71

LAN System (diag)-69

Paper manuals may have different page numbering then what is reflected below, based on multiple new and revised pages. Please refer to the information contained on the STIS web site for all future, update service manual information.

## **INTRODUCTION**

MODEL

Legacy &

Outback

Legacy &

Outback

SECTION

Chassis

Transmission

Chassis

YEAR

2015

2014

2013

2012

2011

ATTENTION:

GENERAL MANAGER

CLAIMS PERSONNEL

SERVICE MANAGER

**APPLICABILITY:** 

PARTS MANAGER

The purpose of this bulletin is to provide a description of current changes to Service Manuals available via the Subaru Technical Information System (STIS) web site. The tables contained within this bulletin are to be used as guides for becoming aware of the latest changes. We advise you to always refer to the STIS web site when looking for the latest Service information. Printed pages will **not** be made available to update printed Service Manuals.

2012-2015MY Impreza 2007, 2010-2015MY Legacy & Outback 2008-2014MY Tribeca SUBJECT: Service Manual Corrections

PAGE(S)

PS(diag)-22,28,29,32

CVT(diag)-41-44.79-86

VDC(diag)-42,43

SERVICE BULLETIN

2013 & 2015MY Forester

2013-2015MY BRZ

© 2015 Subaru of America. Inc. All rights reserved.

IMPORTANT - AII

Service Personnel Should Read and

Initial in the boxes

provided, right.

**DESCRIPTION OF CHANGE** 

Diagnostic steps added for

DTC's C2545, 2546, 2547, U1235, 1433.

Diagnostic steps changed for

DTC's P0716, 2746 & 2750

Diagnostic steps changed for DTC C0028.

Diagnostic steps changed for DTC U1302.

Diagnostic steps changed for DTC U1302.

Diagnostic steps changed for DTC U1302.

NUMBER: 18-181-15 DATE: 06/03/15

Body

Body

Body



QUALITY DRIVEN® SERVICE

YEAR	MODEL	SECTION	PAGE(S)	DESCRIPTION OF CHANGE
2010	Tribeca	Body	LAN System (diag)-71	Diagnostic steps changed for DTC U1302.
2009	Tribeca	Body	LAN System (diag)-75	Diagnostic steps changed for DTC U1302.
2008	Tribeca	Body	LAN System (diag)-90	Diagnostic steps changed for DTC U1302.
		Transmission -	CVT(w/o HEV) (diag)-50-52,112-114,116-118	Diagnostic steps changed for DTC's P0717, 2747, 2751,
2015 Impreza	Impreza		CVT(HEV) (diag)-57-59,62-64,148-150	Diagnostic steps changed for DTC's P0717, 0720, 2751
		Chassis	VDC(diag)-53,54,102,103	Diagnostic steps changed for DTC's C1242, C0028.
2014	Impreza	Chassis	VDC(diag)-45,46	Diagnostic steps changed for DTC C1242.
2013	Impreza	Chassis	VDC(diag)-45,46	Diagnostic steps changed for DTC C1242.
2012	Impreza	Chassis	VDC(diag)-44,45	Diagnostic steps changed for DTC C1242.
2015	Forester	Chassis	PS(diag)-32	Diagnostic steps changed for DTC C2551.
2013	Forester	Chassis	VDC(diag)-44,45	Diagnostic steps changed for DTC C0028.
2015	BRZ	Engine Control	ES-95	Steps added for DTC P000B.
2014	BRZ	Engine Control	ES-95	Steps added for DTC P000B.
2013	BRZ	Engine Control	ES-95	Steps added for DTC P000B.