



SI M51 02 15  
Body Equipment

May 2015  
Technical Service

This Service Information bulletin supersedes SI M51 02 15 **dated April 2015.**

**NEW** designates changes to this revision

#### SUBJECT

**NEW** Service Action: Remove Engine Oil Label

#### MODEL

F55 (Cooper 4-Door Hardtop, Cooper S 4-Door Hardtop)

F56 (Cooper 2-Door Hardtop, Cooper S 2-Door Hardtop, JCW Hardtop 2-Door)

#### SITUATION

Affected vehicles in dealer inventory must not be retailed or delivered until this issue is corrected.

Vehicles at ports of entry will be remedied prior to dealer delivery.

On affected vehicles, there is an incorrect label regarding the appropriate engine oil.

Affected vehicles can be identified with a "Vehicle Comment" in the DCS Warranty Vehicle Inquiry or ISPA Light.

#### CAUSE

The text on the label does not conform to legal regulations.



#### CORRECTION

Remove the label.

#### PROCEDURE

Remove the label using a hot air gun to soften the adhesive. Gently pull the label off while varying the heat. Remove any remaining adhesive with a solvent-based cleaner.

Discard the removed label.

#### **NEW** WARRANTY INFORMATION

Reimbursement for this Service Action will be via normal claim entry utilizing the following information:

<b>Defect Code:</b>	<b>00 71 20 02 00</b>	
---------------------	-----------------------	--

<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 63 597	1 FRU	Remove engine oil label (Plus work)

**ADDITIONAL INFORMATION**

Perform the procedure outlined in this Service Information on all affected vehicles before customer delivery or the next time they are in the shop for maintenance or repairs.

[ Copyright ©2015 BMW of North America, Inc. ]