

Measure no.

US 61177012-01

Subject

DDC control unit can no longer be programmed

Status date (mm/dd/yy)

4/23/15

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

4/23/15

Created by

Bernhard Kistler

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K42

Engine**Body****Production period (from/to)**

(mm/dd/yy)

Comment on production period**Feedback (all cases relating to**

measure up to) (mm/dd/yy)

/

Complaint

When programming the vehicle, the DDC control unit (Dynamic Damping Control) can no longer be programmed.

Cause

This can lead to communications problems during programming.

In rare cases, the hardware reference can then no longer be stored correctly in the DDC control unit.

This fault only occurs if the vehicles software was updated to integration level

K024-14-08-500 or higher.

Measure

Create a PuMA case to schedule a GoToAssist session to reprogram the DDC control unit.

Complaint**Fault location****Fault type****Fault place**

▶ 61/35 ESA control unit Software error

Cause

#	Fault location	Fault type	Fault place
▶ 1	61/35 ESA control unit	Software error	
Repair Task		Special Clearance	Area
		No	Electrics/Electronics

Fault code

Progman / DIS / ISTA / ISTA/P

System	State	Version
--------	-------	---------

© 2002-2015 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.