

Measure no.

US 62085781-01

Subject

Handlebar weight with hand protection

Status date (mm/dd/yy)

8/28/15

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

8/28/15

Created by

Bernhard Kistler

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K49

Engine**Body****Production period (from/to)**

(mm/dd/yy)

/

Comment on production period**Feedback (all cases relating to**

measure up to) (mm/dd/yy)

Complaint

Vehicles with hand protection, the mounting screw for the handlebar weight becomes loose.

Cause

When installing hand protection with handlebar weights, the M10x50 screw has not been secured with Loctite 243.

Measure

When installing the hand protections with handlebar weights, the M10x50 screw must be secured with Loctite 243.

Complaint

	Fault location	Fault type	Fault place
▮	32/71 Handlebar weight	Screw connection faulty	Both sides / all

Cause

#	Fault location	Fault type	Fault place
----------	-----------------------	-------------------	--------------------

1 32/71 Handlebar weight Part connection: Loose

Repair Task	Special Clearance	Area
Retrofit	No	Body and Trim

Fault code

Progman / DIS / ISTA / ISTA/P

System	State	Version
---------------	--------------	----------------

© 2002-2015 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.