



SUBJECT

CAS Module Fails Programming with CoAPI Error 2082

MODEL

E70 (X5)

E71 (X6)

E72 (ActiveHybrid X6)

E82 (1 Series Coupe)

E84 (X1)

E88 (1 Series Convertible)

E89 (Z4)

E92 (3 Series Coupe)

E93 (3 Series Convertible)

Produced from January 15, 2013 to March 30, 2013

SITUATION

During vehicle programming, the CAS (Car Access System) module fails to program with CoAPI error 2082 displayed. Refer to the attachment, which lists the affected CAS serial numbers. The following part numbers are affected:

61 35 9 287 534

61 35 9 226 238

61 35 9 227 053

61 35 9 287 535

PROCEDURE

Replace the CAS module. Finish the previous programming session.

PARTS INFORMATION

Part Number	Description	Quantity
Refer to ETK	Control unit CAS	1

WARRANTY INFORMATION

Covered under the terms of the Limited Warranty for Passenger Cars and Light Trucks.

Covered under the terms of the BMW Certified Pre-Owned Program when necessary and performed in conjunction with the CPO covered repair.

--	--	--

Defect Code:	Refer to KSD2	Claim with the defect code that applies to the previous work that necessitated this additional work procedure to be performed
Labor Operation:	Labor Allowance:	Description:
61 35 516	Refer to KSD	Replacing control unit for car access system
And:		
61 00 721	Refer to KSD	Additional work after first termination while programming/encoding (with CAS)

ATTACHMENTSView PDF attachment [B611515 Attachment.](#)

[Copyright ©2015 BMW of North America, Inc.]