

Measure no.

US 61737304-01

Subject

Protective film on the rear frame

Status date (mm/dd/yy)

7/1/15

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

7/1/15

Created by

Christine Koehling

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K54

Engine**Body****Production period (from/to)**

(mm/dd/yy)

/

Comment on production period**Feedback (all cases relating to****measure up to) (mm/dd/yy)****Complaint**

The protective film (46 51 8 561 402) has not been applied.

Cause

This protective film is applied only to the black frame on the left when viewed in the direction of travel. The attachment contains an image of the protective film.

Measure

No action is required.

This protective film is applied only to the black frame on the left when viewed in the direction of travel.

The attachment contains an image of the protective film.

46 51 8 524 784 Rear frame, black >> 1 x 46 51 8 561 402 protective film

46 51 8 555 831 Rear frame, agate grey >> No protective film

Vehicles with the black rear frame should have the protective film on the left side when delivered.

Vehicles with the agate grey rear frame will not have the protective film and do not need it.

Complaint

Fault location	Fault type	Fault place
↳ Mounting / dismounting	Missing part in production / manufacturing	Rear left

Cause

#	Fault location	Fault type	Fault place
↳ 1	46/51 Frame Front frame, rear frame		Rear left
	Repair Task	Special Clearance	Area
	No action	No	Chassis and Suspension

Fault code**Progman / DIS / ISTA / ISTA/P**

System	State	Version
---------------	--------------	----------------

