



This Service Information bulletin supersedes SI B65 24 13 **dated January 2014.**

NEW designates changes to this revision

SUBJECT

Headunit-High: INITIAL Enabling Code Is Not Accepted Via I-Drive

MODEL

F01 (7 Series Sedan)

F02 (7 Series Sedan)

F02H (7 Series ActiveHybrid)

F06 (6 Series Gran Coupe)

F07 (5 Series Gran Turismo)

F10 (5 Series Sedan)

F10H (5 Series ActiveHybrid)

F12 (6 Series Convertible)

F13 (6 Series Coupe)

F15 (X5)

F22 (2 Series Coupe)

F23 (2 Series Convertible)

F25 (X3)

F30 (3 Series Sedan)

F30H (3 Series Sedan ActiveHybrid)

F31 (3 Series Sports Wagon)

F32 (4 Series Coupe)

F33 (4 Series Convertible)

F34 (3 Series Gran Turismo)

Produced from July 2013 (MY14 vehicles)

With option 609 (Navigation System Professional, HU-H)

and

Without option 6VA (CIC contribution)

SITUATION

The navigation system part of the Headunit-High (HU-H) cannot be activated when entering the 20-digit INITIAL enabling code manually via the iDrive controller.

CAUSE

Application error in the Headunit-High (HU-H).

INFORMATION

Do not replace parts and do not program the vehicle for this issue.

NEW First-time activation of the navigation system should always be performed during the Quality Certification 1 (QC1) Pre-Delivery Inspection (PDI), with the vehicle connected to the ISTA diagnosis system. Refer to [SI B65 22 14](#).

WARRANTY INFORMATION

Not applicable since the first time activation of the navigation system is part of the QC1 process and cannot be claimed separately.

[Copyright ©2015 BMW of North America, Inc.]