

SI B24 02 15 Automatic Transmission June 2015 Technical Service

SUBJECT 8HP: Transmission Fluid Loss from Cooler Lines Connections

MODEL

E84 (X1)

E89 (Z4)

F22 (2 Series Coupe)

F23 (2 Series Convertible)

- F30 (3 Series Sedan)
- F31 (3 Series Sports Wagon)
- F32 (4 Series Coupe)

F33 (4 Series Convertible)

F34 (3 Series Gran Turismo)

F36 (4 Series Gran Coupe)

With the N20, N26, or N55 engine and 8HP transmission

SITUATION

There is a transmission fluid leak in the area around the oil cooler lines (on the transmission side).

CAUSE

Damaged o-rings due to unfavorable cooling line connection tolerances

PROCEDURE

Verify that the transmission fluid leak originates from the cooling lines area.

If so, replace the o-rings and the cooling lines.

Only replacing the o-rings may cause a repeat failure.

PARTS INFORMATION

Refer to the current version of ETK for the appropriate cooling line and o-ring part numbers.

WARRANTY INFORMATION

Please follow the applicable warranty policy and procedures, together with using the corresponding defect code and labor operations in KSD2.

[Copyright ©2015 BMW of North America, Inc.]