



SI B32 05 14
Steering and Wheel Alignment

October 2015
Technical Service

This Service Information bulletin supersedes SI 32 05 14 **dated October 2014.**

NEW designates changes to this revision

SUBJECT

Steering Wheel Does Not Return to Center

MODEL

I01 (i3)

SITUATION

NEW When traveling at speeds of up to 65 mph, the steering wheel may not return to center of its own accord after cornering.

CAUSE

Electronic Power Steering (EPS) rack characteristic

INFORMATION

Do not replace any parts for this complaint.

The return behavior is inherent in the design of the EPS.

NEW An EPS “break in” period of approximately 2000 miles is required.

NEW Once this phase is completed, the level of friction is significantly reduced and no longer affects the return to center.

Please use this information to educate the customer on the “break in” period of the EPS.

WARRANTY INFORMATION

Not applicable.

[Copyright ©2015 BMW of North America, Inc.]