

**Measure no.**

US 61326053-02

**Subject**

Turn signals remain on after alarm is activated

**Status date (mm/dd/yy)**

10/8/15

**Status**

Accepted

**Organization**

US, MOT

**Date created (mm/dd/yy)**

10/8/15

**Created by**

Markus Grosam

**PQM Problem reference****Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

**Vehicles affected****E series**

K17 K48 K49 K50 K51

**Engine**

K52 K53 K54

**Body****Production period (from/to)**

(mm/dd/yy)

**Comment on production period****Feedback (all cases relating to**

measure up to) (mm/dd/yy)

/

**Complaint**

After activation of the alarm system, the turn indicators remain on for 1 minute with integration levels higher than K001-15-03-510.

**Cause**

Software Malfunction with integration level K001-14-08-510 and subsequently with integration levels after K001-15-03-510.

The software malfunction was only removed with K001-15-03-510.

**Measure**

Work on a solution is in progress; The solution is expected to be available with integration level K001-16-03-500 (Spring of 2016)

**Complaint**

<b>Fault location</b>	<b>Fault type</b>	<b>Fault place</b>	<b>Fault conditions</b>
▶ Display: Alarm system	Failure		Sporadic
▶ Flashing	Lights up too bright / glares	Both sides / all	Sporadic

---

**Cause**

#	Fault location	Fault type	Fault place
1	61/35 Alarm system control unit	Software error	
Repair Task	Special Clearance	Area	
Program/encode	No	Electrics/Electronics	

---

**Fault code**

---

**Progman / DIS / ISTA / ISTAP**

System	State	Version
--------	-------	---------

---