

**Measure no.**

US 62177457-01

**Subject**

A fault/defect on the right passenger grab handle

**Status date (mm/dd/yy)**

10/6/15

**Status**

Accepted

**Organization**

US, MOT

**Date created (mm/dd/yy)**

10/6/15

**Created by**

Christine Koehling

**PQM Problem reference****Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

**Vehicles affected****E series**

K49

**Engine****Body****Production period (from/to)**

(mm/dd/yy)

/

**Comment on production period**

about May / June 2015

**Feedback (all cases relating to****measure up to) (mm/dd/yy)****Complaint**

There is a notch visible on the lower part of the right grab handle.

**Cause**

The fault/defect is due to a tooling error.

**Measure**

The rear grab handle (part number 46 54 7 717 014) is to be replaced under warranty.

Note: Vehicles which are affected by SIB "46 001 15 (019) Luggage carrier" get

p/n 46 54 7 717 018 and claimed per the SIB.

**Complaint****Fault location**46/72 Grab handle, pillion  
passenger**Fault type**

Groove / point of impact

**Fault place**

Rear

**Cause****#****Fault location****Fault type****Fault place**

1	46/72 Grab handle, pillion passenger	Groove / point of impact	Rear
	<b>Repair Task</b>	<b>Special Clearance</b>	<b>Area</b>
	Replace	No	Body and Trim

---

**Fault code**

---

**Progman / DIS / ISTA / ISTA/P**

<b>System</b>	<b>State</b>	<b>Version</b>
---------------	--------------	----------------

---

© 2002-2015 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.

