

Measure no.

US 62332524-01

Subject

Transmission Downshifting

Status date (mm/dd/yy)

11/30/15

Status

Accepted

Organization

US, MOT

Date created (mm/dd/yy)

11/30/15

Created by

Carsten Gruetzmacher

PQM Problem reference**Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

Vehicles affected**E series**

K70/11 K71/11 K72/11 K73/03

Engine

K75

Body**Production period (from/to)**

(mm/dd/yy)

Comment on production period

/

Feedback (all cases relating to**measure up to) (mm/dd/yy)**

Complaint

Occasionally it's not be possible to downshift the transmission; especially from 3rd to 2nd gear.

Cause

Gearshift shaft and free gearwheel.

The vehicles affected are those produced in 2015.

Measure

With a verified customer complaint by a BMW certified technician and confirmed via puma exchange, replace the gearshift shaft and free gearwheel.

See image in the accompanying picture, parts 1 and 2.

Note: The transmission does not have to be disassembled.

Refer to latest ETK for model specific part numbers.

This repair is on a case by case basis, applicable within the scope of the original warranty

Complaint

Fault location	Fault type	Fault place	Fault conditions
23/00 Manual gearbox	Shift characteristics not OK		Shift down

Cause

#	Fault location	Fault type	Fault place
1	23/00 Manual gearbox		
	Repair Task	Special Clearance	Area
		No	Powertrain

Fault code**Progman / DIS / ISTA / ISTA/P**

System	State	Version
---------------	--------------	----------------

