



NUMBER: 08-002-15

GROUP: Electrical

DATE: January 08, 2015

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

SUBJECT:

P41 Interim Repair Procedure Brazil ONLY

OVERVIEW:

Some Jeep Commander and Jeep Grand Cherokee vehicles may experience an unintended change in ignition switch position while driving which may result in loss of engine power, power steering, and braking assist increasing the risk of a crash and disabling one or more of the vehicle's safety features including the frontal airbags.

Chrysler intends to repair the vehicle free of charge (parts and labor). However, the part required to provide a permanent remedy for this condition is currently not available.

MODELS:

2005-2007	(WK)	Jeep Grand Cherokee (Brazil only)
2006-2007	(XK)	Jeep Commander (Brazil only)

NOTE: This bulletin applies to vehicles in the Brazil market only.

NOTE: This bulletin will be cancelled when parts become available.

REPAIR PROCEDURE:

1. Adjust the driver seat to allow clearance between the driver's knee and the ignition key.

NOTE: All drivers of the vehicle should adjust the seat to allow for sufficient clearance between the drivers knee and the ignition key.

2. Remove all items from the key ring, leaving only the vehicle key.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
08-80-32-94	P41 Interim Ignition Key Obstruction	6 - Electrical and Body Systems	0.2 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------