

GPOP - Issue Review System

Part Number: 68141898A\$, 04779897A\$

Part Description: Sensor - Rear ABS Wheel Speed

Issue Description: Prior to replacing a rear wheel speed sensor with one of these two fault codes C0037-4A (left rear wheel speed sensor – incorrect component installed) or C003A-4A (right rear wheel speed sensor – incorrect component installed), please call Jason Sekhon on his cell at (248) 941-8782. If he doesn't respond within 15 minutes, please continue with the repair.~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.