

GPOP - Issue Review System

Part Number: 68080819A\$

Part Description: Camshaft Position Sensor

Issue Description: If replacing a camshaft position sensor for P0340 and/or P0344 fault codes, please review information below and contact Andrew Acton on his cell phone: (248) 421-4130. If no response is received within 15 minutes, please continue with repair.~

Before clearing any codes please pull Freeze Frame and CamCrank Sync Event Monitor data (instructions below) from the PCM and send the PDF's to Andrew Acton by email: andrew.acton@fcagroup.com~

Instructions to access CamCrank Sync Event Monitor:~

- From wiTECH main screen~
- Monitors tab~
- OBDII Monitors~
- Select Cam Crank Synchronization Event Monitor from the list~
- Should bring up 3 or 4 pages of data~
- Click on create PDF icon in lower right corner~
- email PDF to andrew.acton@fcagroup.com ~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
