

GPOP - Issue Review System

Part Number: 1VH87DX9A\$, 5LH34DX9A\$

Part Description: Air Bag Module - DRIVER

Issue Description: Before replacing this part, due to horn not working, please contact Chuck Hood at cell (248) 613-7591. If you don't receive a response within 15 minutes, then continue with repair procedure.~

~

~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
