GPOP - Issue Review System

Part Number: 68080819A\$

Part Description: Camshaft Position Sensor

Issue Before replacing the camshaft position sensor for P0340 or P0344 fault codes, **Description:** please call Andrew Acton on his cell (248) 421-4130. If no response is received

within 15 minutes, please continue with repair.

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.