

**SUBJECT****Delivery Stop: Rear Side Window****MODEL**

F25 (X3)

F26 (X4)

**SITUATION**

A Delivery Stop has been issued on vehicles produced from August 13, 2015 through August 14, 2015. These vehicles may have had the rear side window adhesive incorrectly applied.

Affected vehicles in dealer inventory must not be retailed or delivered until this issue is corrected. Vehicles at ports of entry will be repaired prior to dealer delivery.

This bulletin will be updated with instructions and warranty information when it becomes available. Please contact your field representatives if you have any questions.

The affected vehicles can be identified with a "Vehicle Comment" in DCS Warranty Vehicle Inquiry or ISPA Light with the description:

- Defect Code 0051760300, Delivery Stop, Rear Side Window, see SI B51 29 15.

[ Copyright ©2015 BMW of North America, Inc. ]